

✓

TOTAL INSPECTIONS
117
TREND ▲ 91 %

+

POSITIVE OBSERVATIONS
1,510
TREND ▲ 88 %


—

NEGATIVE OBSERVATIONS
631
TREND ▲ 78 %

🗑️


TOTAL OBSERVATIONS
2,141
TREND ▲ 85 %

Observations




Report Score:71%

Inspections vs Report Score




Top 5 Categories (Of Issues)




Top 10 Negative Observations

	Sub-Category	Count
1	Chemicals (in secondary container) properly labeled/legible? 1910.1200	11
2	Aisles/passageways appropriately marked? 1910.22(b)(2) Interp Letter	5
3	Lifting hooks have functional safety latch? 1910.179(j)(2)(iii)	5
4	Compressed air kept under 30 psi at nozzle? 1910.242(b)	3
5	Cylinders secured to prevent tipping? 1910.101	3
6	Fall protection provided/used at unprotected surfaces 4+ ft? 1910.28(b)	3
7	Lift operated on smooth/level surface? ANSI/SIA A92.2, 3, 5, 6, & 7	3
8	Elevation changes delineated to minimize trip hazard? (Best Practice)	2
9	Aisles/walkways kept clean and orderly? 1910.22(a)(1)	2
10	Aisles proper width (at least 3 ft. wider than largest equip. or min.	2


Inspections by Company




Average Score by Company



Inspections by Inspector







Average Score by Inspector




eCAT Dashboard

Use this dashboard To analyze your Corrective Action Tracking.



11/03/2017 - 11/02/2018



Open: 151
Pending: 4
Closed: 110

11/03/2017 - 11/02/2018

	Open	Pending	Closed	% Closed
NOV 2018	0	0	0	0%
OCT 2018	38	0	6	14%
SEP 2018	4	0	4	50%
AUG 2018	0	0	8	100%
JUL 2018	32	1	24	42%
JUN 2018	10	0	9	47%
MAY 2018	25	1	20	43%
APR 2018	5	0	18	78%
MAR 2018	24	2	12	32%
FEB 2018	7	0	4	36%
JAN 2018	0	0	3	100%
DEC 2017	0	0	0	0%
NOV 2017	6	0	2	25%